

27 AUG 1958

Received from Chief Ship Surveyor.....

SHIP'S NAME "BELGRAVE" REPORT Sou. No. 24993  
AR.

Outstanding Conditions of Class: Subject to indented side shell plating etc. (p & s.f) being dealt with by next Special Survey.

Endorsement of Certificate (As before ~~XXXXXX~~)

Surveys due: SPECIAL SURVEY (C) due 9,58. Postponement until 9,59 approved 7.7.58, provided a satisfactory General Examination is held.

Nature of Present Survey: (Afloat and in dry dock) Docking and General Examination, as above; permanent/deferred repairs on account of damage (cause not stated); equipment - removal of 30 fathoms of defective chain cable.

Special Features: None.

Interim Certificate in order (Yes ~~No None~~)

Items Outstanding: (If any for S.S.) All. *Items*

S.S. to be completed by:

Recommendation: SUBMITTED record of 'DS 7,58' be assigned, SUBJECT as above, and to permanent repairs being effected to indented shell plate D.5 etc. (p.s. from fwd) at the Special survey, and to 30 fathoms of chain cable being supplied at the earliest opportunity.

DS 7,58. Subject.

S.R.L. APPENDIX.

Shell plate F.10 (s.s.f) indented. A number of keel and bottom shell plates (p & s) and stem bar slightly buckled.

IT IS FURTHER SUBMITTED postponement of the S.S. until 9,59 merits approval.

*JS*  
*14-8-58*



© 2021

Lloyd's Register Foundation

013260 + 013267 + 013