

Plating is drilled the results must be reported on Report 8(Eq). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

Rpt 14.

Port of Aioi Japan

June, 12, 19 61

### REPORT ON MASTS, SPARS, AND RIGGING.

Kobe Rpt. 8 No. 9138

*Having, in accordance with your instructions,*

*examined the Masts, Spars, Iron Work of same, and Rigging, of the*

*Name of Vessel) TAIEI MARU*

*on the (Date of examination) June 9, 19 61*

*have to report that I found*

- Fore mast, rigging and accessories ..... Good condition*
- Midship posts, rigging and accessories ..... Good condition*
- Main mast, rigging and accessories ..... Good condition*

*S. Ogata*

ISHIKAWAJIMA-HARIMA HEAVY INDUSTRIES CO., LTD.  
SHIP DIVISION, AIOI NO.1 WORKS.

*the Surveyors,  
Lloyd's Register of Shipping,*



© 2021

Lloyd's Register  
Foundation

013284-013292-0149

A.S.