

Diameter of tube holes in drum 4.047  
If Drum has a flat side state method of staying

Engine No. 6/1358 Made by Babcock & Wilcox Ltd.  
Boilers

For Hong Kong & Whampoa Dock Co.'s No. 819

Report No. 61661


It is submitted that a copy of this Report be  
forwarded to the H.K. Surveyors for their  
returned guidance and for completion, & this report be retained  
in the Birmingham Office pending completion.

Date

20/10/39

Im. 6,36.

Photostat copy of  
report sent H.K.  
6/11/39



© 2021

Lloyd's Register  
Foundation

013390-013396-0253

16/10/39

the approved plan of boiler for