

Ship's name ^{SS.} "DJAJAPRATAMA"

Port Kobe

-3 JUN 1965

No. 14319.

Class is subject to None.

Last survey date 2/5/65.

S.P.S. (due 4/64) commenced 8/64, not completed. ^{re-commenced.} Repairs.

Fabricated end cover + division plate fitted to main condenser (Broken) but cover ~~was~~ found to be deflecting under pressure (plate not thick enough) & the Surveyor recommends that the main condenser aft end cover and division plate (temporary repair 5/65) be renewed at earliest opportunity.

It is submitted that the vessel **WILL BE** eligible for the record S.P.S. 5/65 when the survey has been completed, by examination and

testing of the saturated steam pipes in boiler smoke-boxes, subject as not recommended.

3/6/65. Thru J. Kodama

The Surveyor should be informed that the steam pipe survey was held at Kobe in 8/64, R.P. No. 13232, but the saturated steam pipes in the boiler smoke-boxes were not tested and the record of S.P.S. 8/64 was withheld pending this being done (see ^{YKA} correspondence).

His comments why the survey was not completed as requested and he should state what arrangements can be made for completion. When inspecting a subject against an item, the surveyor should be asked to file a precise date in future, a precise date and avoid the use of indefinite terms.

