

"IRVINGDALE 1"

Refer St.John, N.B. cable of 30.3.66.

IT IS SUBMITTED the Surveyors be advised that a certificate of fitness to be towed could be issued provided they are satisfied with the condition of the ship for the proposed voyage after a General Examination in dry dock in accordance with the requirements of Instructions to Surveyors, Part 3a, 1963, Para.6, Section 2 and Amendment No.7, also the remaining requirements of Instructions to Surveyors, Part 11, 1954 "Towage Surveys" complied with where applicable.

The Surveyors to satisfy themselves on stability in conjunction with Owners.

Certificates to state towage arrangements are the responsibility of the Owners and the class is suspended during the voyage.

The Report 10 should be headed "Seaworthy Certificate" (in relation to technical characteristics).

*MB*  
30.3.66.

*Surveyors to be guided by Unit to Survey Part II,*

*30/3/66*

© 2021  
*Q*  
30.3.66.  
Lloyd's Register  
Foundation