

EA

COPY

Ship's name "IRVINGDALE I"

Port S.Jn

No. 3160

Class is subject to

Last survey date 5.9.63.

indented shell plates E.1 & 2, F.1, G.1 & 2 (p.s) E.1,
F.1 and G.1 (s.s) and indented bottom shell plates
No.3 keel plate and A.3 & 4 (p.s.from aft) being
specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix (~~as before~~ or none)

Nature of present survey (afloat and in drydock)

Permanent repairs to damage caused by contact.
S.R.L.

Recommendation

SUBMITTED record of DS 9,63 be assigned,
subject to indented shell plates E.1 & 2, F.1,
G.1 & 2 (p.s) E.1, F.1 and G.1 (s.s)
being specially examined and dealt with as
necessary next drydocking, without other conditions.

DS 9,63 Subject
without.

INSERT IN S.R.L.APPENDIX.

Bottom shell plates No.3 keel plate and
A.3 & 4 (p.s.from aft) indented.



© 2021

Lloyd's Register
Foundation