

17 JAN 1964

Ship's name "CAMPERO" Port Cdz No. 3508

GB Class is subject to wasted shell plates Last survey date 28.10.63.
from aft and indented shell plate C.5 (S.S.), D.7 (P.S.)
B.6 (P.S.F) etc. being specially examined and dealt with as necessary by the S.S.

S.R.L. Appendix (as before ~~XXXXXXXX~~ or none)

Nature of present survey (afloat and in drydock)

Docking: Examination of S.R.L. and S.R.L. Appendix items:
Minor wear and tear repairs.

Recommendation

SUBMITTED record of 'DS 9,63' be assigned,
subject as above.

DS 9,63 Subject

~~IN S.R.L. APPENDIX.~~
Indents in keel plating.



© 2021

Lloyd's Register
Foundation
30.12.63