


# Lloyd's Register of Shipping

UNITED WITH THE BRITISH CORPORATION REGISTER

BRITISH COLUMBIA

1718 MARINE BUILDING

VANCOUVER 1, B.C.



R. Riddell, Esq.,  
Principal Surveyor for Canada,  
Montreal.

Dear Sir:-

"YSF 216", "YSF 217", "YSF 218"  
"YSW 220"

Further to our letter of the 5th instant advising you progress in connection with the survey of the above R.C.N. Union Lighters and Water Boat, we have to advise you that these vessels have now been under survey at H.M.C. Dockyard, Montreal.


A drydocking survey was carried out on "YSF 216", "YSF 218" and "YSW 220" but "YSF 217" was drydocked in March May last without this Office being notified. A copy of the R.C.N. docking report is attached to our Report in this case and we trust this will be accepted as a docking survey meanwhile.

An Annual Loadline survey was carried out on "YSF 216", "YSF 217" and "YSF 218" but not on "YSW 220" which is not due until December next.

The Committee reports intended for London are being forwarded to you together with the Montreal copies and it is requested that you will kindly forward these to London after dealing with such comments as you may think necessary.

We conclude these Naval Auxiliary vessels will be withdrawn from classification sooner or later as has been done in the case of other Naval Auxiliary vessels built to Class in recent years.

Yours very truly,

  
Lloyd's Register  
Foundation  
For the Surveyors.

RP/A  
ENCLOSURE

013750 - 013759 - 0018

2