



LLOYD'S REGISTER OF SHIPPING

OFICINA CENTRAL: 71, FENCHURCH STREET, LONDON, E. C. 3

Calle Langreo, n.º 4, 9.º Gijón

5th April, 1967

Telegramas: Register

Teléfono 349513

Referencia:
C
DNS/DET..

Dear Sir,

S.S. "JOSIÑA"

With reference to your letter of the 8th ult. we enclose herewith an amended Rpt.8(A).

It is confirmed that the full requirements of an Annual Classification Survey were carried out.

Regarding the entries "good in parts examined" we have to advise you that:-

- a) Ventilator and air pipe coamings were found good on weather decks but in 'tween decks and holds complete examination would have entailed removing lining and casings.
- b) Side scuttles and deadlights in ships side and superstructure were found good, but in deck houses above superstructures these were not examined.
- c) Scuppers and sanitary discharges with valves (as far as practicable) were found good.

We regret that the F.P. spaces were not examined.

Yours faithfully,

J. Russell

For the Surveyors.

The Secretary,
LONDON.-



Lloyd's Register
Foundation

013950-013960-0118

REPORTS

Mob

sr

Hoted
R7-c
19-4-67



© 2021

Lloyd's Register
Foundation