


COPY

# LLOYD'S REGISTER OF SHIPPING



Port

GIJON

4th November, 1965

**This is to Certify** that I have surveyed part of the  
machinery of the **S.S. JOSINA, 3314** Gross tons of Bilbao  
for MBS, drydocking survey, tailshaft survey, oil fuel conversion,  
repairs and condition of class.

and that all my recommendations have been carried out to my satisfaction.

I am reporting accordingly and recommending to the Committee of Lloyd's

Register of Shipping that the ~~machinery classification should be retained~~

~~and the following survey records assigned~~ re-classification of the ship's  
machinery be confirmed with fresh record of BS4,63 now and SPS 2,63  
now as previously recommended and MBS 10,65 and TS(CL) 10,65 subject  
to the main engine M.P. and L.P. crosshead pins (electrically welded)  
being specially examined by the end of October 1966 and subject to any  
**Parts now examined:—** outstanding conditions of class being dealt  
with as previously recommended.

Propeller and all outside fastenings.

Port, centre and starboard boilers internally and externally with  
mountings and safety valves and the safety valves adjusted under steam.  
Oil burning system and remote controls.

Tailshaft.

**NOTE.** Salt water evaporator not to be used until surveyed.

*R.M. Hobson*

R.M. Hobson.

Surveyor to Lloyd's Register of Shipping

## KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey  
CSM Continuous Survey of Machinery  
DBS Donkey Boiler Survey  
ES Engine Special Survey  
MBS Main Boiler Survey  
OP Fitted for oil fuel (date) FP above 150° F.

SGS Steam Generator Survey  
SPS Steampipe Survey  
TS Tailshaft Survey  
TS(CL) Tailshaft Survey—Continuous Liner  
TSN Tailshaft renewed  
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

«While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society».

013950-013960-0140

