

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
 Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

25th August, 1964

C
DNS/RW

Dear Sirs,

m.v. "PORT JACKSON"

The Report of the survey carried out by the Society's Melbourne Surveyors between the 30th ultimo and 3rd instant, has now received the consideration of the Committee.

At that time, repairs were effected by welding to the starboard aft outboard main engine air compressor L.P. piston, which was found to be cracked, and it was recommended that this item should be specially examined by the end of January, 1965.

The Committee have continued the vessel's class subject, inter alia, to this matter receiving attention by that time.

Yours faithfully,

pro Clerk to the
Classification Committee

The Port Line Ltd.,
Cunard House,
88, Leadenhall Street,
LONDON E.C.3



© 2021

Lloyd's Register
Foundation

013961-013971-0035