

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME Stb S "ROBIN"

Rpt. (Yps) Under No. 92280

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.*—Extract from Sub-Committee's Report, 24/5/92.)

Survey P. Gentry

It is submitted before this case receives the consideration of the Committee the surveyor should be requested to state whether the side keelson angles, the bridge deck beams as hull angles, the size of the raised quarter deck trough beams, the thickness of the deck plating ^{RUDDER PLATE} the riveting of the hull plating at Starboard and Sheerstrake are as approved, and not as stated in the report. The Surveyor should also be requested to forward particulars of the streamline supplied.

Dr. 9/5/28



© 2021

Lloyd's Register
Foundation

014253-014262-0282