

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

14th February, 1928.

Dear Sir,

S. With reference to your First Entry report No. 92280 on the machinery of the s.s. "ROBIN", I have to request that you will state whether the thrust shaft is 5.75 inches diameter under the collars as entered on your report, in view of the fact that by the Rules it should be not less than 5.9 inches.

I am, Dear Sir,

Yours faithfully,

Clerk to the
Classification Committee.

A. R. Farminer. Esq.,

IPSWICH.



© 2021

Lloyd's Register
Foundation

014253-014251-0284

Do

Also for Mr. S. A. Hill to note.

Robert G. ...

STENOGRAPHIC ...

... ..

... ..

... ..

... ..

... ..

... ..

... ..

СОБЪ.



© 2021

Lloyd's Register Foundation