

Sc. Totara

Hul. 36940.

Before this case receives consideration, submitted
the Hull Surveyors be requested to state why the
automatic indicators for the navigation lamps
have not been fitted & they should state
what arrangements have been made for the
Rule requirements in this respect to be
complied with.

D. J.

6/4/06.

Lloyd's Register
Foundation

014513 - 014530 - 0349