


C O P Y

LLOYD'S REGISTER OF SHIPPING

Kobe Rpt. 9 No. 13986

No. B1-114891



Port KOBE

23rd February, 1965

This is to Certify that I have surveyed part of the machinery of the **m.s. "AKI MARU",** **7,733** **Gross tons** of Tokyo for CSM, ABS, TS(CL) Starboard and Damage whilst she lay in drydock and afloat at Osaka on the 9th February, 1965 and subsequently

and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned **ABS 2,65, TS(CL) (S) 2,65 and CSM (with date)** on completion, subject to any outstanding condition of class being dealt with as previously recommended.

Parts now examined:—

For Docking: Port & Starboard Propellers, Starboard Tailshaft, All sea connections and Fastenings.

For CSM:

Main engine:

P. No.3 & S.No.2 cyls., covers, pistons & rods and valves & gears.
P. No.3 & S.No.2 con. rods, crossheads, bearings & guides.
P. No.3 & S.No.2 crankpins and bearings.
P. No.8 & S.Nos.1,5 & 7 journals and bearings.
Main engine driven scavenge pump P. Nos.3,4 & 5 & S.No.2 cyls., covers, pistons and rods and levers.
P. & S. Nos.3 & 4 Intermediate shafts and their bearings.

Auxiliaries:

Ballast pump. Port inboard feed water pump.
Stb'd outboard O.P. service pump. Port inboard O.P. transfer pump.
Stb'd air compressor, coolers and safety devices throughout.
S. outboard O.P. service tank for M.E.
S. outboard D.O. service tank.
Port forward generator diesel engine in its entirety.

For ABS:

Auxiliary boiler throughout.

M. Kitan

Surveyor to Lloyd's Register of Shipping

M. Kitan

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CSM Continuous Survey of Machinery
DBS Donkey Boiler Survey
ES Engine Special Survey

MBS Main Boiler Survey
OF Fitted for oil fuel (date)
SGS Steam Generator Survey
SPS Steampipe Survey

TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

HK:sk

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B.1 - 10,64 KOB

014744-014806-0068