

1

action is deferred for drydocking (grounding), for a special survey & repairs.

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME Islandside. REPORT Bal. No. 9668.For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/62.)

Nature of Survey Special survey (B). When due 11.51.Noted

Without Special Conditions.

5.52 Bal.

S.B. Bal. 5.52.

Delete Endorsement of Class (B) itemOffice note:-

No 3 O.B. Tank top stiffened
locally (p.s.f). Bal. 5.52.

Delete from S.B.L.
Drydocking (grounding).



© 2021
22-7-52.

Lloyd's Register
Foundation

014 815 014 826-0267