

RECEIVED

COPY.

W.J. YARWOOD & SONS LD.
NORTHWICH.

12th September, 1952.

We are in receipt of yours of 5th instant with enclosure. We think that the proposal made by the Committee of Lloyds to fit a stream anchor on the forecastle is impracticable. The anchor could not be handled by the davit which is on the starboard side of the ship. The position of the stream anchor is on the forward side of the after bulkhead, where it is as handy as it possibly could be.



© 2021

Lloyd's Register
Foundation

014827-014834-0125

014827-014834-0126