

Ship's Name ~~S~~/MS "LUCIANO CASTRO"
 L.R. 521364 Port of Registry Santos Port of SANTOS
 Gross tons 600
 Date of build 3-1950 Is there a Rpt. 9? Yes Rpt. No. 4449
 No. of visits 1 First date and Last date 13.9.65
 Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only) Jan 42/6
 Date of completing rpt. 20.10.65 Surveyed at, if different from Port above --
 Surveyed afloat and/or in D.D. Drydock Last date of examination in D.D. 13.9.65
 Has a Load Line Survey been held? No Summer freeboard as verified --
 State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig) P.S.
 Survey fees Damage fee Expenses Cables Cr\$ 36.168
 Dkg Cr\$ 70.000
 S.A. fee

29/1/66

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due

I have surveyed the above-named ship in accordance with the Rules for DOCKING.

Condition of Class (Chain cable).

The Owners have stated that new cable has been ordered and will be fitted immediately on receipt.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. I recommend, therefore, that this ship remain as classed with/without fresh record of dry docking D.S. 9.65 subject to all outstanding conditions being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

G. A. Stewart
G. A. Stewart

Surveyor to Lloyd's Register of Shipping

MONDAY 24 JAN 1966

Deferred for cons Re classin
(Equipment)

Lloyd's Register
FOR CHAIRMAN
CLASS. CITE

ALSO FOR
SPL FOR
TR
SRL
POSTING
HEADER
CERT

Rpt. 8 (P.S.) DRY CARGO SHIP

Ship's Name /MS "LUCIANO CASTRO"

S.S. (-) Due

L.R. 521364

Port of SANTOS

Rpt. No. 4449

<u>Examined & condition</u>		<u>Examined & condition</u>	
In dry dock from	13.9.65	* Air & sounding pipes	
" " " to	15.9.65	Doublers under " "	
Shell plating	Good	Steering arrangements (main)	Good
Sternframe	Good	" " (aux)	Good
Rudder	Good	Windlass	Good
Was rudder lifted?	No	Masts & rigging	
Plating, etc. in way of shell openings	Good	Hand pumps & suction	
Side scuttles & deadlights	Good	W.T. doors	
Overbd. scuppers & discharges	Good	Bulwarks, freeing ports, etc.	Good
F.P. spaces		Summer freeboard as verified	
Chain locker			
A.P. spaces			
Engine space			
Boiler space			
Under E. & B.			
Coal bunker			
Tunnel & well			
Cement, asphalt, etc., on btm. shell			
Weather decks	Good		
* Casings	Good		
* Deckhouses	Good		
* Superstructures	Good		
* Skylights	Good		
* Companionways	Good		
* Hatchways	Good		
* Ventilators	Good		
Other items:			

EQUIPMENT:

Equipment letter	h
Fee ltr., if diff. from eqpt. ltr.	
Anchors: No. on board	4
State if ranged	No
Length on board	Stated complete
Mean dias. range from	to
Rule length	Dia.
Mooring ropes	Sufficient

* These items to include their closing appliances
Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"



© 2021
G. A. Stewart
Surveyor to Lloyd's Register of Shipping

Foundation