

1 Henry Robb Ltd. Leith.

Yard No. 379

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

GB

VESSEL'S NAME T.S.M.V. "MOMBASA"

REPORT

Lth

No. 22467

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24 / 5 / 92.)

Nature of Survey First Entry

When due.....

The scantlings have been approved for the class 100A1 "With freeboard", corresponding to a summer moulded draught of 14'-6".

100A1 "With freeboard"
1.50 Lth.

1 Dk 2nd Dk forward of Mch space "pt Elec. welded"
Cell DB 188' 468t, Tanks at sides of tunnels 7lt, FET 57t, APT 25t.

PK, 5BH, Lloyd's A & CP

P & B 156' F 28'


O.L. 265.8'

ESD

Radar

"r"

1/2"



© 2021



E.H.D.

3.5.50

Lloyd's Register
Foundation