

RECEIVED LONDON OFFICE
SECTION FOR REPAIRS, &c.

Lon No. 127773

When handed in at Local Office No. 19 Port of London
Date, First Survey Last Survey

Material or Steel s/s "ALGARROBO" (No. of Visits)

Built at BURNTISLAND By whom BURNTISLAND S.B. CO. LD. When 1924 MONTH 6

Owners NAVIERA CHILENA DEL PACIFICO S.A. Owners' Address 1924

Managers Port belonging to VALPARAISO

Dock? Name of Dock Destined Voyage

feet: uE&B feet: f feet: tons: APT tons: MT tons: feet: tons: Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Existing records of tanks should be inserted. Particulars in the existing records should be underlined.

No. 3219 Port VPO.

+ 100 A 1 9,52 + LMC 9,52
SS VPO (14) 9,48 BS 7,62
Reclassed 12,51 TS CL 12,51
Large bottom not fitted

Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the date and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE FOR

SUMMARY OF DAMAGE REPAIRS:	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed, ...								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Caulking of Decks	Cement or Asphalt	Oil Bunkers	Boats
Coamings	Rudder	Scuppers	Masts, Yards, &c.
Beams & Fastenings	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
Outside Plating	Windlass	Hatches	Equipment letter
" " in way of sidelights	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Reverse Frames	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diam. (on board.)
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Transverses	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Floors	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Keelsons		" " at other places	Standing and Running Rigging
Stringers		Stringers, Clamps & Shelves	Sails
Inner Bottom Plating		Salting	
Have the Tanks been examined internally?		State if examined	
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 23)	£	:	:	Fees applied for,
Damage or Repair Fee (if any) (per Sec. 23)	£	:	:	19
Living Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

FRIDAY 16 OCT 1953

Surveyor to Lloyd's Register of Shipping.

GENERAL COMMITTEE

Thursday 5 November 1953

Classing Committee's decision confirmed.

Character Assigned White

It draws class and insert (...) J.H.

In Certificate required? If so, to be sent to

014899-014911-0289