

E6 MAR 1950

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

VESSEL'S NAME "HUMBERGATE" REPORT Nwc. No. 106987

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH cause not stated.

One blade of the propeller was missing. Screwshaft now examined, stern bush remetalled and a new propeller fitted.

IT IS SUBMITTED that this vessel is eligible
for the record S 2. 50.



© 2021

Lloyd's Register
Foundation

3. 3. 50.