

COPY

LLOYD'S REGISTER OF SHIPPING



Port Liverpool

17th July, 1964.

we

This is to Certify that I have surveyed part of the machinery of the m.v. "INTERPRETER", 6815 Gross tons of Liverpool

for Damage stated to have been sustained during passage from Galveston to Manchester on the 6th May, 1964, and Advancement of Continuous Survey of Machinery whilst the vessel lay afloat at Birkenhead on the 25th May, 1964, and subsequently,

our ~~xxx~~ and that all my recommendations have been carried out to my satisfaction. ~~xxx~~ We are ~~xxx~~ am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following ~~XXXXXXXXXXXXXXXXXXXX~~ survey records assigned ~~XXXXXXXXXXXXXXXXXXXX~~ subject to any outstanding conditions of class being dealt with as previously recommended.

Parts now examined:—

Main Engine.

- Nos. 1 & 5 cylinders, pistons, rods, valves and gears, transverse beams and bottle guides.
- No. 5 centre and side connecting rods, top ends and guides.
- No. 5 centre and side crankpins and bearings.
- No. 6 journal and bearing.
- Holding down bolts and checks.

Auxiliaries.

- Outboard lub. oil pump.
- Port outboard generator engine.

A. Jackson
Surveyor to Lloyd's Register of Shipping
A. Jackson (for R. Gregory & self).

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150°F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

015183-015187-0026