

"INTERPRETER" orig on "CROFTER".

4



LLOYD'S REGISTER OF SHIPPING

Reliance House, 20, Water Street, Liverpool, 2

Telegrams: Register, Liverpool


Telephone: Central 8891 (5 Lines)

Reference

EJB/ID.

Your Ref: C. AH/EA.

7th February, 1967.



Dear Sir,

Ships owned by T. & J. Harrison Ltd.
4 yearly Screwshaft Surveys.

I have to thank you for your letter of the 6th instant, with enclosed copy of communication respecting the "GOVERNOR", and await further letters in due course in respect of the "INTERPRETER" and "PLAINSMAN".

The Screwshaft Survey of the "JOURNALIST" was carried out in Liverpool in March, 1966 (Liverpool Report No. 168249) and the Surveyor states that crack detection was carried out in accordance with the Owners' routine, although no mention of this was made in the report. I shall, therefore be glad if you will furnish a letter in this case, also approving 4 yearly Screwshaft Surveys.

With regard to the "CROFTER", I would point out that according to the Owners' statement, the drydocking in March, 1966, was carried out at Glasgow (not Liverpool as stated by you) and perhaps you will be so good as to communicate with the Glasgow Office to ascertain whether in this case also crack detection was carried out but not reported.

Yours faithfully,

Secretary to the
Liverpool Committee.

The Secretary,
LONDON.



© 2021

Lloyd's Register
Foundation

015183-015187-0082