

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex  
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

6th February 1967.

ENCLOSURE

C  
AH/BA

Dear Sir,

Motorships "GOVERNOR", "INTERPRETER",  
"PLAINSMAN", "JOURNALIST" & "CROFTER".

4 YEARLY SCREWSHAFT SURVEYS.


I refer to the telephone conversation with you today concerning the above mentioned ships and the position is as follows:-

"GOVERNOR".

It has been agreed that surveys of the screwshaft may be carried out at intervals of four years, and in this respect I refer you to my letter to the Owners of the 3rd November 1966, a copy of which is enclosed for easy reference.

"INTERPRETER" & "PLAINSMAN".

The screwshafts of these ships were drawn for inspection in June 1966 at Manchester and in July 1966 at Liverpool respectively. Crack detection tests were carried out, although no mention of 4 yearly surveys appeared in the survey reports, nor was a request received from the Owners for the extended survey period. We will be writing to the Owners through your office during the course of the next few days authorising future surveys to be held at 4 yearly intervals.



Lloyd's Register  
Foundation

015183-015187-0083 12




"JOURNALIST" & "CROFTER".

The screwshafts of these ships were drawn for inspection at Liverpool in March 1966, but no mention of crack detection tests is made in the reports nor have we had any requests for surveys to be held at intervals of four years. Your further instructions in regard to these cases are awaited, and it is appreciated that crack detection tests may have been made, but not mentioned in the relevant survey reports. two

Yours faithfully,

pro Classification Manager.

The Secretary,  
LIVERPOOL



© 2021

Lloyd's Register  
Foundation

0083 1/2