

ing Gear, type (Power or hand)

5/8" dia ✓

Alternative Means of Steering

2 Cylr "Southern Cross" Diesel, with clutch & countershaft

Windlass from Ford Winch. (Larkeneave Boats 2 @ 12)

17 APR 1946

(Received at London Office..... 19..)

No. 129

Place SYDNEY. N.S.W.

Date 5th February 19 46

We request that the Committee of Lloyd's Register will instruct the Society's Surveyors to survey the Twin Screw Motor Vessel "TANDJONG OEBAN", with a view to classification.

We undertake to arrange for every facility to be given to the Surveyors to carry out the duty in question, and we agree to pay the fees for the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connexion therewith.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:-

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

Frederick Miller for  
Standard Vacuum Oil Co.

To the Secretary,

Lloyd's Register of Shipping,

71, Fenchurch Street, London, E.C.3.

26 Broadway New York

015338 - 015347 - 0234

No cement laid on bottom

Lloyd's Register Foundation