

4E

subject to

10 OCT 1961

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

"MARE NOSTRUM"

REPORT

Nap.

No. 7284


Docking. Screwshaft examined.

MBS due 11.61, partly held 8.61, not advanced.

Screwshaft liner found eroded, now skimmed and cone crack detected and found in good order, stern bush rewooded.


IT IS SUBMITTED that this vessel is eligible to remain as classed with fresh records of TS (CL) 9.61 now and MBS 8.61 when the survey is completed.

9.10.61



To complete MBS

The safety valves of the Port and Starboard Boilers to be adjusted under steam and the oil burning system to be examined under working conditions.



© 2021
Lloyd's Register
Foundation
015366-016379-0374