

No. 4693

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report Dec 15 1893 When handed in at Local Office Dec 15 1893 Port of Aberdeen

No. in Reg. Book. Survey held at Aberdeen Date, First Survey Dec 12 Last Survey Dec 14 1893

on the Wood, Iron or Steel S.S. "North East" (No. of Visits 3) Master Sutherland

TONNAGE:- Built at Aberdeen By whom Hall Russell & Co When 1890 8

GROSS 123 Owners W. Pyper Port belonging to Aberdeen

UNDER DK. 111 Owners' Address

NET 25 (If not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Slipway Name of Dock A Hall & Co's Slip Destined Voyage Trawling

WB=DBa tons; f tons; uE&B tons; CellDB tons; Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

Last Survey, No. 4575 Port Abw

(Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
100 A 1 5.93 Stm. Trawler		2 m to 8.90

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Sighting Bottom

The vessel placed on the above slipway, the bottom examined and found in good condition, and afterwards repainted

One plate in the sheerstrake on the starboard bow indented, has been faired in place. It is not known when this damage was received

SUMMARY OF DAMAGE REPAIRS:—Plates, Faired or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE

Decks Good	Transoms, Pointers, & Crutches Good	Copper, or Y.M. (State if on Felt.)	Hatches Good
Waterways	Timbers of Frame at the openings	When put on, Month Year	Boats
Coamings	Ditto ditto at other places	Rudder Good	Masts, Yards, &c.
Up'r Dk. Beams & Fastenings	Keelsons	Windlass & Capstan	Condition, how ascertained from dk.
Low'r Dk. Beams & Fastenings	Clamps, Shells & Stringers	Pumps	Sails
Plating	Salting (State if examined.)	Engine Room Skylights	Equipment letter for Trawlers
Planking	Coiling	Coal Bunker, Open'gs, Lids, &c.	Anchors, No. of 3
Trunnels or Rivets	Cement or Asphalt (State which.)	Scuppers	Cables (State if now ranged) No.
Breasthooks & Stemson	Tanks (State if now tested.)	Cargo & Main H'tch'ys	length 60 ft size 1 1/2 in.
	Caulking of Bot'm, D'k, & Wat'r'ys		Rule length size
			Hawsers & Warps Good
			Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This vessel so far as seen is in good and efficient condition and eligible in my opinion to remain as classed and to be noted 12, 93. in the Reg. Book

Office Fee (if chargeable) per Scale II., Sec. 27	£	Fees applied for,
Survey Fee (per Section 28)	£	18
Special Damage or Repair Fee (if any) (per Sec. 28.)	£	Received by me,
Travelling Expenses (if chargeable)	£	18
Second Surveyor's Fee (if any)	£	

*Is Certificate now required?

Committee's Minute

Character assigned

TUES. 19 DEC 1893

100A

Stm. Trawler

Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2019

Lloyd's Register Foundation

ABN 11-0320

* Certificate, if required, to be sent to

Form No. 2 for Repairs.—205.—L.R.P.H.—10,000.—9/8/82.—Transfer Ink. (The Surveyors are requested not to write on or delay the space for Committee's Minute.)