

It is submitted that this vessel's machinery will not be eligible for any class until the survey upon the machinery & boilers has been completed. There remains to be done the examination of the donkey boiler throughout with its safety valves, examination of the tail shaft & details of the machinery, including the bridge inspection valve which if not found to be a non return valve should be made such.

J. J. M
31/7/90



© 2018

Lloyd's Register
Foundation

ANT1103A/25



01
© 2018

19 3 1 3
Lloyd's Register
Foundation

カ
8
2