



Lloyd's Register of British & Foreign Shipping,

Dock Chambers,

Barry, 29th. May, 1908.

LLOYDS REGISTER,
LONDON.
REC'D 30 MAY 1908
ANSE

Sir,

With reference to your letter of the 1st. February last, and my report No. 9744 on the steamer "DERWENT", I beg to draw your attention to the fact that this vessel's boiler pressure is incorrectly recorded in the Register Book.

I am, Sir,

Your obedient Servant,

Andrew Couper

The Secretary
LONDON.



© 2021

Lloyd's Register
Foundation

Referred to the Chief Engineer Surveyor.

FMU.

MAY 30 1933

Also for Mr. S. A. Hill to note.



© 2021

Lloyd's Register
Foundation

Is a Report also sent on the Hull of the Ship?

whether and when, one will be sent?

MU
(Leds
Boil
No.
safet
Are
Sma
Mat
Des
Lap
rule
Des
plat
Top
sma
Pit
Are
Lou
Pit
wat
gira
Wo
sepe
hol
If s
Wa
D
of
u
bu
G
Sh
fi
h