

S.S. "CORNWALL".

It is submitted the Owners be informed that from the examination of the stern frame made by me on the 29th instant, and the recommendation made that a steel shoe plate be fitted to the sole piece as a permanent repair, no other repair is in my opinion necessary to efficiently deal with the damage referred to.

C.B.

C.F.

31.1.13.



© 2021

Lloyd's Register
Foundation