


S. S. "CORNWALL"

Mr. Clericf, the intending Buyer of this Vessel, with Mr. Henderson, his representative, called here this morning and stated that in removing a stud bolt from the sole piece of the stern frame a cavity was discovered which could not be seen at the previous examination. Mr. Henderson stated they were the Owners of the vessel and requested that the sole piece should be further examined and reported upon in view of the above. They were informed that no survey could be made of the Ship at their request until they produced evidence of Ownership.

As it is desirable that the fullest information should be in this Office regarding the stern frame, it is submitted that Mr. Hand, the Society's Principal Surveyor at Cardiff, be requested by telegram to make a further examination of the sole piece in way of the stud hole and report the result of his examination. The examination should be made as early as possible before the steel shoe is fitted.

C.B.

E. b. b.



31.1.13

© 2021
Lloyd's Register
Foundation