

No. 4887

(Received at London Office)



TESTS OF BOILER STEEL

Tests of 10 Steel Plate manufactured by Messrs D Colville & Sons of Glothenwell
 for Boiler No. 256 to be constructed by Messrs W. B. Thompson & Co of Dundee
 for their S. S. 1081

Date first visit May 18th 1887 last visit May 30th 1887 No. of visits

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to _____ samples as set forth below, and the temper and bending tests to a shearing from each plate with satisfactory results.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.	
					Thickn.	Brdth.	Area.	Total.	Sq. Inch			
					Ins.	Ins.	Ins.	Tons.	Tons.	%		
1	$10.7\frac{1}{4} \times 52\frac{1}{2} \times \frac{1}{2}$	M141			276	.49	1.54	.754	21.11	28.0	27.0	
2	- x - x -	C879			3809	.50	1.98	.990	29.97	30.2	22.0	
						.50	1.68	.840	25.10	29.8	22.0	

RF.
2/6/87

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by

© 2019

 H. Dowse
 Surveyor, Lloyd's Register
 Glasgow
 31.5.87