

# ANNUAL SURVEYS.

331

No. 331 Survey held at Glasgow Date 16<sup>th</sup> April 1850  
 on the Ship "Vulcan Caesar" Master Martin Fleming  
 Tonnage 610 Built at New Brunswick When built 1838  
 By whom built 1838 Owners Lampert  
 Port belonging to Liverpool Destined Voyage Washington  
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 9379 Port of Liverpool Classed 4 E, 1  
S. S. - 47 - 4 Cur

The Surveyor is required to state the present Condition of the

Decks	Transoms	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.
Spirkettling	Wales	Sails
Plank Shears	Counter	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
Breasthooks	Windlass	Copper

General Observations and Opinion, This ship has been working at her Beam Ends and appears to be considerably strained; badly  
as required by the Instructions, in her Upper Works, One Hold Beam Hanging Knee broken at the throat, several Bolt started  
the side of the knees off the side.  
17<sup>th</sup> April, handed the Master a Card Addressed to the Owner, Recommending as highly desirable, that as the ship  
has been working and considerably strained and leaky, and One Hold Beam Knee broken, that the Deck  
and Hold Beams be additionally fastened with new Hanging Knees and that the started Bolts be driven out and renewed.

Committee Minute 26<sup>th</sup> April 1850  
30<sup>th</sup> April

Character assigned

Broken knee replaced and Caulked where necessary  
The vessel has proceeded on her voyage to Washington where the Master states she is to be repaired

No. 331 Survey held at Dumbarton Date 22<sup>nd</sup> April 1850  
 on the Knack "New Odd Fellow" Master William Livingston  
 Tonnage 60 Built at Dumbarton When built 1847  
 By whom built Dunlop & Rankin Owners Livingston  
 Port belonging to Dumbarton Destined Voyage Liverpool  
 If Surveyed Afloat or in Dry Dock Patent Ship

Last Survey, No. 2234 Port of Chm Classed 6 A, 1

The Surveyor is required to state the present Condition of the

Decks	Transoms	Mast	Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame	Pumps	
Lower Deck Beams & Fastenings	Topsides	Masts, Yards, &c.	
Spirkettling	Wales	Sails	
Plank Shears	Counter	Cables	
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of	
Hatchway Comings	Rudder	Standing & Running Rigging	
Breasthooks	Windlass	Copper	

General Observations and Opinion, At Present Caulked the Bottom  
as required by the Instructions, is in good condition and may continue as classed

Committee Minute 26<sup>th</sup> April 1850

Character assigned



© 2019

Lloyd's Register  
Foundation

1150-041575