

# Report of Survey for Repairs, &c., of Engines & Boilers.

7821

No. 4821 Port of Glasgow (Received at London Office, MONDAY 23 FEB 1887)  
 No. in Survey held at Glasgow Date, first Survey 14 Feb 77 Last Survey 21 Feb 77 1887  
 Reg. Book. 844 on the Machinery of the S. S. "Clan Stuart" (Number of Visits 5)  
 Year Month  
 Tonnage, Gross 2094 Built at Glasgow When built 1879-2  
 Ditto, Net 1355 Owners Cayzer Irvine & Coy Port belonging to Glasgow  
 Diameter of Cylinder 36" + 66" Engines made by David Rowan When made 1879  
 Length of Stroke 42" Boilers made by " " When made 1879  
 Pressure of Steam 80 If Surveyed Afloat or in Dry Dock Both (State Name of Dock.)  
 Registered Horse Power 280 Classed 100 A.1  
 Last Survey No. 10786 Port Lloyds M.C. 5/86

## Particulars of Repairs and Examination

(State clearly the cause of Repairs if any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Engines opened up and all working parts examined, pistons  
 slide valves & pumps overhauled, Crank shaft examined, Propeller  
 Shaft replaced by the spare one, Cocks, valves and all connections  
 examined & overhauled in dry dock  
 Main & Donkey Boilers examined throughout also the  
 Safety valves & other connections

## General Observations, Opinion, and Recommendation :—

(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

The machinery & boilers of this vessel are now in good order  
 and safe working condition & eligible in our opinion to  
 be noted in the Register Book + L.M.C. 2/87

Office or Registration Fee (per Sec. 27) £ : :  
 Survey Fee (per Section 28) £ 3 : 3 :  
 Special Damage Fee (per Section 28) £ 1 : 1 :  
 \*Certificate (if required) £ : :  
 Travelling Expenses (if chargeable) £ : :

received by me,  
 25/2/87 1887

James Morrison John Sanderson  
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

TUESDAY 1 MARCH 1887

Assigned

L. M. C. 2/87

Clyde District  
 Lloyd's Register  
 Foundation  
 GLS153-0131



1821/87

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

Was submitted that this vessel is  
eligible to have the notification  
No 2.87 recorded the boilers  
being subject to resurvey  
as per table

DP  
28/2/87



© 2019

Lloyd's Register  
Foundation