


- Copy -



We the undersigned have Carefully Considered the reports of the Divers who had made examination of the hull &c of the Ship "Cedarbank" - and are of opinion that - as the stempost is, with all gudgeons, reported to be in good Condition while the brackets and pintles of rudder, with the rudder itself appear to be strained - We recommend that the rudder be unshipped and landed - and all defects & vents made good as may be discovered on further examination.

Sape Inon

Augth 2nd 1897

(Signed)

W. Stephen
Marine Surveyor

H. Haswell
Engineer Surveyor



© 2021

Lloyd's Register
Foundation

GRK338-0126