

F.E.

by Chief Surveyor 4. 3. 99

Received from Chief Surveyor

NAME SA S. S. "Raithwaite" Report Spel No. 10802

e remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required ~~and~~ to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>4/20"</u>	<u>Proportions</u>
Spar Sheerstrake . .	<u>✓</u>	<u>✓</u>
Description of Framing:— <u>Deep framing. 1/20" thicker than required.</u> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ± 100 A1 ("Steel") as recommended.

± 100 A1 ("Steel")

1 DR (Em) 2 to B & deep framing. 3 DR Rule.

W. B = Cell DB a & u E 130' f 136' 7156 APT 516

FK. 5BH Cam. A & CP.

C. H. P.
4/3/99



© 2019

Lloyd's Register
F001384-0088.1