

Received by Chief Surveyor 13-7-99

Received from Chief Surveyor

VESSEL'S NAME *SS S/S "Clam"*

Report *My*

No. *98*

(Hull only)

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

Damage stranding

The Lloyd's Agent at Algiers forwards a report stating that this vessel, extensively damaged through stranding, has been temporarily repaired by means of wood planking &c. A number of photographs shewing the damage and progress of repairs are attached.

The vessel is proceeding to an East Coast port ^(Sunderland) for permanent repairs.

As the class is expunged from the Register Book, and the "Stranded & refloated" recorded, it is submitted further action is at present unnecessary, beyond informing the Sunderland Surveyors.

HPL387-0136

For Mr. Hill to note

→ write Sld. *THM* 13-7-99

[Signature]
13/7/99
Lloyd's Register
Foundation