

2 Enclos.

All communications on this  
subject to be addressed to  
THE SURVEYORS,  
LLOYD'S REGISTER OF SHIPPING,  
HULL.

D.

Lloyd's Register of British & Foreign Shipping.  
Hull Jan<sup>y</sup> 1<sup>st</sup> 1884

Ans 19

The Secretary.

Sir,

In reply to your letter of the 15<sup>th</sup> instant, with enclosures, having reference to the S/S "Rosario", I beg to remark that this vessel was surveyed by both Mr. Williams and myself during construction and that no defective work was observed; the Builders as well as the Society's Surveyors being always most careful as to the quality of the work and anxious to keep up the reputation of the port.

On the return of the vessel from her first voyage she was placed on the slipway, and repairs as enumerated in the Owners' letter were carried out by the builders to put the vessel into thorough good condition, but as the Manager did not consider these repairs

18/1/84  
J.M.



© 2020  
Lloyd's Register  
Foundation

more than usually required, I was not informed by him that such repairs were being done and therefore did not see them.

I would remark that the vessel while fitting out was aground each tide and this is the only cause I can account for the defects.

I much regret that the Owner should have any reason to make the first Complaint, and I am much surprised at the postscript he added to his letter dated the 14<sup>th</sup> inst, as I have always heard the S/S "Mareugo", belonging to them and built under my Survey, spoken of as the most satisfactorily built vessel in their fleet.

The Owners Letters relative to this case are herewith returned.

I am,

L © 2020  
Your obedient Servt,  
James M. Peel

1883.  
Kull, 17 Jan

Surveys

Rec: 18

Ans: 19

"Rosaris"  
(W)



© 2020  
Lloyd's Register  
Foundation