

REPORT of SURVEY for REPAIRS.

No. 5777 Survey held at London Date Oct 10 1839
 on the Ship Pestoye Bonaparte Master M. Kile
 Tonnage 595 Built at Bombarton When built 1835
 By whom built _____ Owners Maddell & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Atcham Lock

Original Survey, No. _____ Dated 1838 Classed 12A1
 Port London

Repairs

*as the present time stopped - Cables and
 up & reappearing - knee of head refitted fastened
 & bottom reappearing*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

*In my opinion she is entitled to remain
 as classed 12A1*
George Bayley

The Amount of Fee.....£ : : is received by me,

Committee's Minute _____ 18 _____

Character assigned _____