

REPORT of SURVEY for REPAIRS.

Coppering

5886

No. 332 Survey held at London Date Dec^r 7 1839
 on the Bk Alexander Johnston Master Donald Mc Donald
 Tonnage 289 Built at Dunbarton When built 1835
 By whom built _____ Owners Mr Sarty
 Port belonging to Greenock Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 114 Dated 1835 Classed 12 A 1

Port of Greenock

Repairs At Hambro's September 1838 caulked
& Coppered over paper

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c. <u>Good</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Sails <u>&</u>
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables <u>Efficient</u>
Hatchway Comings	Rudder	Anchors No. of _____
Breasthooks	Copper	Standing & Running Rigging _____

General Observations and Opinion, Is in a very high state of efficiency both in the
 as required by the Instructions, Hull & Stores & eligible to retain her present Class

W. Doleman

The Amount of Fee.....£ 1 : 1 : _____ is received by me, HS

Committee's Minute 12 Dec 1839

Character assigned 12 A 1 und off

