

REPORT of SURVEY for REPAIRS.

11399

No. 92 Survey held at London Date Feb²² to Mar⁶ 1845
 on the Brig "Harmony" Master J Gibson
 Tonnage 205 Built at Ayr When built 1813
 By whom built _____ Owners W Thompson
 Port belonging to _____ Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Duke Shore Dock

Last Survey, No. 1564 Classed *A. 1

Port Glyde

REPAIRS now done, of damages sustained by being struck with the sea in her recent passage from Havannah.

Ny 29 feet of double Bulwark and Rail also 7 Stantions on the Lait quarter, one Stantion Stail^e, both upper Head Rails, the lower Planks of Square Tuck, and the Huls of Star Timbers secured.

The Vessel Caulked from lower edges of Walls upwards to second seam of Deck.

Not of damage. The Yellow Metal stripped off, the Fir Sheathing, Caulked, and the Bottom re-sheathed with Yellow Metal. False Keel renewed & Keel Seam Caulked.

A Pair of Pointers and a Crutch of Iron now introduced.

Present Condition of the

| | | |
|-------------------------------|----------------------------------|----------------------------|
| Decks | Treenails | Windlass and Capstan |
| Waterways | Breasthooks and Stemson | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Keelsons | Sails |
| Planksheers | Clamps and Shells | Anchors No. of |
| Sheerstrakes | Ceiling | Cables |
| Topsides | Rudder | Hawsers and Warps |
| Wales | Copper | Standing & Running Rigging |
| Plank (Bottom) and Counter | Y Metal now new upon | |

General Observations and Opinion,

We are of opinion that this Brig is fit for the safe conveyance of dry & perishable Cargoes to and from all parts of the world and should be allowed

The Amount of Fee.....£ 1 : - : - is received by me,

Certificate (if required) : 10 : -

Committee's Minute 11th March 1845

Character assigned A. 1 asterisk

the civil (Survey)

Record repair