

REPORT of SURVEY for REPAIRS.

& Change of Owners

No. 279 Survey held at London Date Nov 4 1848
 on the Bk Mittinger Watson Master Marrison
 Tonnage 432 Built at Dunbarton When built 1845
 By whom built _____ Owners P Henderson
 Port belonging to Glasgow Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 2375 Classed 10 A1

Port of Sunderland

REPAIRS Has been in dry dock & bottom examined

Present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>good & strong</u>	Timbers of the Frame <u>sound & good</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>good</u>	Sails <u>well found</u>
Planksheers <u>Good</u>	Clamps and Shells <u>"</u>	Anchors No. of <u>3 Bowers & 1 Stn 2/4</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>well found</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>yellow metal 1847</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion, From her very firm sufficient appearance and of opinion she may retain her present class

The Amount of Fee.....£ 2 : - : - is received by me,

Certificate (if required) : 10 : -

Committee's Minute 10th Nov 1848

Character assigned 10 A1



© 2019

Lloyd's Register Foundation

LON 625-0408