

Change of owners from division 15581

# REPORT of SURVEY for REPAIRS.

No.

419

on the

Survey held at

London

Date

Nov<sup>r</sup> 12<sup>th</sup> 1849

Master

J C Edwards

Tonnage

420

Built at

Greenock

When built

1839

By whom built

Owners

W Rogers 23 East Dr. Chambers

Port belonging to

London

Destined Voyage

California

If Surveyed Afloat or in Dry Dock

Afloat had been in Nelson St

Last Survey, No.

1346

Port

London

Classed

10 A1

## REPAIRS

### Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

### General Observations and Opinion,

The Ceiling is in a bad state in many places in the lower hold also the timber shows the inner end of the beams present a suspicious appearance also the lower hook and lower ~~hook~~ part of apron the

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 13<sup>th</sup> November 1849

Character assigned Expunge Character

LONG27-0311

hold beams are 7 feet apart and she has the appearance of being generally weak but notice to the owners of her condition by act no attention had been

Lloyd's Register Foundation