

REPORT of SURVEY for REPAIRS.

17920

No. ⁵²

Survey held at

Change of Surveys
London

Date

Dec 16th 1852

on the

S Panther

Master

H Hannant

Tonnage

420

Built at

Greenock

When built

1841

By whom built

Owners

J. Timlin

Port belonging to

London

Destined Voyage

Sydney

If Surveyed Afloat or in Dry Dock

London Dock

Last Survey, No.

9494

Port

Lpool

Restored

1849

Classed

8

5 A 1

REPAIRS

At Calcutta in January last shipped, caulked from the keel to the gunwale & sheathed with yellow metal on felt

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of 3 Bowers Stm & Kedge

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

From her general firm & efficient state am of opinion she may continue as classed

The Amount of Fee.....£ 2: is received by me,

Special.....

Certificate (if required)

Committee's Minute

24th Decr 1852

Character assigned

See P 5 A 1



Lloyd's Register Foundation

LON 632-0378