

Douglas Tucker

17963

REPORT of SURVEY for REPAIRS.

No. 373 Survey held at London Date Jan^y 3 1853
on the S John Cooper Master R. Gilkison
Tonnage 522 Built at Greenock When built 1840
By whom built _____ Owners R Gilkison
Port belonging to Glasgow Destined Voyage Bombay
If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 2837 Port Clyde Classed 10 AD
Count 50 3 50

REPAIRS At Bombay her last voyage in April 1852 was shipped, 31 feet of
new false keel, caulked from the keel overall & sheathed with
yellow metal on Gulgal

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, Is in a very good condition to retain her present class

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : 0

Certificate (if required).....

Committee's Minute 14th Jan^y 1853

Character assigned Cont 3 1/2

Record Em L D



© 2019

Lloyd's Register
Foundation

LON 632-0421