

Change of Property- REPORT of SURVEY for REPAIRS.

19810

No. 173 Survey held at London Date 27th & 29th June 1855
 on the Brig "Diana" Master _____
 Tonnage 228 Built at Glasgow When built 1837
 By whom built _____ Owners W. A. Parker & Co
 Port belonging to London Destined Voyage Lagos
 If Surveyed Afloat or in Dry Dock Gun ways & dry dock
Srps 47 & 53

Last Survey, No. 17973 Port London Classed C 3 ¹⁰ * Clap
ss. 53. 53 smith

REPAIRS Now done:- Yellow metal sheathing stripped off and renewed
on paper, and vessel caulked throughout, including flat of upper decks -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>Good and</u>
Lower Deck Beams & Fastenings <u>Good where</u>	Keelsons <u>Good where</u>	Sails <u>sufficient</u>
Planksheers <u>seen</u>	Clamps and Shelves <u>seen</u>	Anchors No. of _____
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>YM</u> When put on <u>now</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways all re-caulked

This brig is in a good and efficient state of repair, fit
for the safe conveyance of dry and perishable cargoes to and from all
parts of the world, and eligible, in our opinion, to remain as classed

The Amount of Fee.....£ / : : is received by me,

Special..... / : / : -

Certificate (if required) : 5 : -

Committee's Minute 24th July 1855

Character assigned B, 1st class

Special Attendance £1 u 1 u 0

Report YM



© 2019

Lloyd's Register
Foundation

LON636-0106