

20000

Recd. 5/1/18
Cash

REPAIRS

The defective shifts of deck have been renewed also the
after hatch Comings, but the Ceiling is not put into that
efficient state which we think it should be, for the present
Class.

Decks	part new - Good	Treenails	Good when seen	Windlass and Capstan	
Waterways	"	Breasthooks and Stemson	" "	Pumps	
Comings	"	Transoms, Pointers, and Crutches	Good when seen	Boats	
Upper Deck Beams & Fastenings	} Good when seen	Timbers of the Frame	" "	Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Keelsons	" "	Sails	} Good and Sufft.
Planksheers		Clamps and Shelves	" "	Anchors No. of	
Sheerstrakes	} Good when seen	Ceiling	partly defective	Cables	
Topsides		Rudder	good when seen	Hawsers and Warps	
Wales		of Metal		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper on Telt	When put on 1834		

Caulking of Bottom, Deck, & Waterways. Good

We are of opinion that she is fit for the safe Conveyance
of dry and perishable Cargoes, but that her character should
be reduced to F. 1. without the Asterisk —

B. Weymth

J. F. Light

Committee's Minute 6th November 1855

R. 1 onuttu retorik

© 2019

Lloyd's Register
Foundation

LON636-0297