

27154

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 371 Survey held at London Date 8th to 23rd November 1865
on the Ship "John Bright" Master Not appointed
Tonnage 541 Built at Dumbarton When built 1847
By whom built _____ Owners Jane & Co.
Port belonging to Furness Destined Voyage Not fixed
If Surveyed Afloat or in Dry Dock Comps Dry Dock and London Dock

Last Survey, No. 26418 Port London Classed 12 A 1
Rest 62 - 8 yrs - 1964

REPAIRS

Now done:-

Bottom sighted and the Yellow Metal patched. The following have been renewed:- viz.
Two Hold Beams - arms, Foremast Mast Partners and two Half-beams to ditto with English Oak. 12 Treennails in the Starboard Topsides and 10 in the Port Topsides with Locust.

Present Condition of the

Decks		Treenails <u>a few new</u>		Windlass and Capstan	
Waterways	<u>fine</u>	Breasthooks and Stemson		Pumps	
Comings	<u>good</u>	Transoms, Pointers, and Crutches	<u>good</u>	Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	<u>where</u>	Ditto Ditto at other places	<u>where</u>	Condition, how ascertained <u>By enquiry and observation from deck</u>	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of <u>3 B. 15. 2 R.</u>	
Topsides	<u>seen</u>	Ceiling	<u>seen</u>	Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <u>F. & M.</u> When put on <u>1864</u>		Standing & Running Rigging	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen

She is now in good and efficient condition, and fit, in our opinion, for the safe conveyance of dry and perishable cargoes, to and from all parts of the world, and to remain as classed.

The Amount of Fee.....£..... is received, by me,

Special..... 1 : 1 : -

Certificate (if required) : 5 : -

Committee's Minute 22nd December 1865

Character assigned Rest^d & A 1

J. Williamson

W. Cornish



© 2021

Lloyd's Register Foundation

LON 650-0231