

ANNUAL SURVEYS.

43038
WEDNESDAY 10 OCT 1883

No. 267 Survey held at London Date, first Survey 3 Sept Last Survey 5 Oct 1883
 No. in Reg. Book. on the S Ben Gouran Master J Shaw
 Tonnage Net 1571 Built at Glasgow When built 1881 8
 Gross 1750 By whom built H Murray Owners Watson Bros
 Under Deck 1780 Port belonging to Glasgow Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Gleno St & Victoria Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 28295 Port of Liv Classed 100A-8.82

Present Condition of the		Treenails		Character in Register Book.	
Decks	<u>Good</u>	<u>Round</u>	<u>Good</u>	Years assigned.	
Waterways	"	Breasthooks and Stemson	"		
Comings	"	Transoms, Pointers, and Crutches	"		
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"		
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"		
Planksheers	"	Keelsons	"		
Sheerstrakes	"	Clamps and Shelves	"		
Topsides	"	Ceiling	"		
Wales	"	Rudder	"		
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Painted</u> When put on <u>new</u>	"		
Engine Room Skylights	<input checked="" type="checkbox"/>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>		
Coal Bunkers, Openings, Lids, &c.	<input checked="" type="checkbox"/>	Scuppers	<u>Good</u>		
General Observations, Opinion as to Class, &c.	<u>Bottom & coated.</u>				

She is now in an efficient state and eligible to remain as classed.

Committee's Minute FRIDAY 12 OCT 1883
 Character assigned 100A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 177 Survey held at London Date, first Survey 2 Oct Last Survey 3 Oct 1883
 No. in Reg. Book. on the S Opawa Master H Mathers
 Tonnage Net 1076 Built at Glasgow When built 1876 11
 Gross 1221 By whom built A Stephen Owners New Zealand Ship Co
 Under Deck 980 Port belonging to Lyttelton N Z Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Poulton Victoria St Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 41923 Port of Low Classed 100A-11.82

Present Condition of the		Treenails		Character in Register Book.	
Decks	<u>Good</u>	<u>Round</u>	<u>Good</u>	Years assigned.	
Waterways	"	Breasthooks and Stemson	"		
Comings	"	Transoms, Pointers, and Crutches	"		
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"		
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"		
Planksheers	"	Keelsons	"		
Sheerstrakes	"	Clamps and Shelves	"		
Topsides	"	Ceiling	"		
Wales	"	Rudder	"		
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Painted</u> When put on <u>new</u>	"		
Engine Room Skylights	<input checked="" type="checkbox"/>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>		
Coal Bunkers, Openings, Lids, &c.	<input checked="" type="checkbox"/>	Scuppers	<u>Good</u>		
General Observations, Opinion as to Class, &c.	<u>Bottom & coated.</u>				

She is now in an efficient state and eligible to remain as classed.

Committee's Minute FRIDAY 12 OCT 1883
 Character assigned 100A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

(Form No. 3 for Annual Survey, when there are no repairs. 4000-15/5/83.)
 (If a Steam Ship, state if a Report is also sent on the Machinery.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (Insert Character precisely as in Register Book.)

(Form No. 3 for Annual Survey, when there are no repairs. 4000-15/5/83.)
 (If a Steam Ship, state if a Report is also sent on the Machinery.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (Insert Character precisely as in Register Book.)

