

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 2-3-97 When handed in at Local Office 2-3-97 Port of London  
No. in Survey held at London Date, First Survey 24-2-97 Last Survey 27-2-1897  
eg. Book. 372 on the Wood, Iron or Steel S/S. Cayo Romano Master Widgery  
(No. of Visits 3) YEAR. MONTH.

TONNAGE:— Built at 8 Shields By whom J Readhead & Co When 1893-9  
GROSS 2600 Owners (Bigland & Co mgt) Port belonging to London  
UNDER DE. 2523 Owners' Address  
NET 1735 (if not already recorded in Appendix to Register Book.)

Surveyed At or in Dry Dock Dry Dk Name of Dock Melwall Dk Destined Voyage Antwerp Cuba  
New Orleans  
WB=Cell D Board 222 feet; uE&B feet; f feet; }  
Total capacity 574 tons. FPT tons; APT tons; MT feet tons. }  
N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.  
Last Survey, No. 3768 Port See ant

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).  
CHARACTER.  for Special Survey. Date of last Survey and of Periodical Surveys. Years Assigned expired. Machinery and Boiler Surveys (including date of N.B., if any).  
+ 100A 1. Spar Dk + Linc 9/93  
Society's Freeboard (if assigned) as painted on Ship and now verified } 5 ft. 9 1/2 ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

This steamer was placed in dry dock, the bottom examined cleaned & recoated. The steering chains overhauled.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Faired or Repaired ...								
PRESENT CONDITION OF THE	<u>Good</u>		<u>Good</u>		<u>Good</u>		<u>Good</u>	
Decks	Timbers of Frame at the openings		Rudder		Hatches		Boats	
Waterways	Ditto ditto at other places		Windlass & Capstan		Masts, Yards, &c.		Condition, how ascertained	
Coamings	Keelsons		Have Pumps now been examined and found efficient?		Sails		Equipment letter	
Up'r Dk. Beams & Fastenings	Stringers, Clamps & Sholes		Have Sluice Valves now been examined and found efficient?		Anchors, No. of		Cables (State if now ranged)	
Low'r Dk. Beams & Fastenings	Salting (State if carried out.)		Have Watertight Doors now been examined and found efficient?		length size		Rule length size (per Table 22)	
Plating	Ceiling		Dbng. Plates under Sounding Pipes		Hawsers & Warps		Standing & Running Rigging	
Painting	Cement or Asphalt (State if now tested.)		Engine Room Skylights		Cargo & Main H'tch'w'ys			
Stowage	Tanks (State if now tested.)		Coal Bunker, Open'gs, Lids, &c.					
Stowage	Caulking of Bot'm, D'k, & Wat'r'w'ys		Scuppers					
Stowage	Copper, or I.B. (State if now tested.)							
Stowage	When put on, Month							

General Observations, Opinion as to Class, Recommendation, &c.:—  
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."  
This steamer now appears to be in a sound and efficient condition, eligible in my opinion to remain as classed with a fresh record of survey Lou 2 197

Survey Fee (if chargeable) per Scale II, Sec. 27 ..... £ : :  
Survey Fee (per Section 28) ..... £ : :  
Special Damage or Repair Fee (if any) (per Sec. 28.) ..... £ : :  
Selling Expenses (if chargeable) ..... £ : :  
And Surveyor's Fee (if any) ..... £ : :  
Fees applied for, ..... 18.....  
Received by me, Edward F W Terney  
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute FRI. MAR 5 1897  
Character assigned 100A Spar Dk  
Lloyd's Register Foundation  
Lon 712 - 0057